




# SGDV-120A01A

Model: KMA-1











# INSTALLATION DIAGRAM FOR CONTROL CABINET





## 10. TROUBLE SHOOTING

Table 9

Trouble	Possible causes	Correction
1. Running out of cutter	<ol style="list-style-type: none"> <li>1. Not accurate for cutter edges</li> <li>2. Not accurate for cutters' holder</li> <li>3. Dirty inside the spindle hole</li> </ol>	<ol style="list-style-type: none"> <li>1. Regrinding the cutter edges</li> <li>2. Replace new one</li> <li>3. Clean it</li> </ol>
2. Chatter	<ol style="list-style-type: none"> <li>1. Tool shank too long or too fine</li> <li>2. Lack of rigidity in the machine, fixture, or workpiece</li> <li>3. Spindle bearing too loose or worn</li> <li>4. Feed rate too high</li> <li>5. Dull of cutter</li> <li>6. Cutting angles of cutter not proper</li> <li>7. Back-lash of feed screw too loose</li> <li>8. Gib of table too loose</li> </ol>	<ol style="list-style-type: none"> <li>1. Replace suitable one</li> <li>2. Improve rigidity</li> <li>3. Adjust or change it</li> <li>4. Reduce feed rate</li> <li>5. Resharpen it</li> <li>6. Regrind it</li> <li>7. Adjust by the adjustable nut</li> <li>8. Adjust by the adjustable screws</li> </ol>
3. Poor surface finish	<ol style="list-style-type: none"> <li>1. Feed too high</li> <li>2. Dull tool</li> <li>3. Speed too low</li> <li>4. Insufficient number of cutter teeth</li> </ol>	<ol style="list-style-type: none"> <li>1. Reduce feed or increase cutting speed</li> <li>2. Resharpen it</li> <li>3. Increase surface speed of cutter</li> <li>4. Adding more teeth for cutter</li> </ol>
4. Vibration	<ol style="list-style-type: none"> <li>1. Loose of levelling screws</li> <li>2. Torn or mismatch of V - belt</li> <li>3. Motor out of balance</li> <li>4. Unbalance of pulley</li> </ol>	<ol style="list-style-type: none"> <li>1. Tighten it</li> <li>2. Replace with new set</li> <li>3. Replace it</li> <li>4. Replace it</li> </ol>
5. Cutter burns	<ol style="list-style-type: none"> <li>1. Insufficient lubricants</li> <li>2. Speed too high</li> </ol>	<ol style="list-style-type: none"> <li>1. Add more sulfur base oil</li> <li>2. Reduce speed</li> </ol>
6. Teeth bearing	<ol style="list-style-type: none"> <li>1. Feed too high</li> <li>2. Lack of rigidity of workpiece</li> </ol>	<ol style="list-style-type: none"> <li>1. Reduce feed</li> <li>2. Improve design of workpiece or fixture</li> </ol>
7. Out of dimension of workpiece after taking off from fixture	<ol style="list-style-type: none"> <li>1. Not suitable of fixture</li> <li>2. Some residual stress in the inside of workpiece</li> <li>3. Rough surface</li> </ol>	<ol style="list-style-type: none"> <li>1. Improve design of fixture</li> <li>2. Improve heat treatment</li> <li>3. Refinishing</li> </ol>
8. Stepped machining surface	Center line of spindle not in perpendicular to table or slide way of carriage or bed	Readjust it correctly

11. MAINTENANCE SCHEDULE

Table 10

ITEM	POSITION	FREQUENCY			
		DAILY	WEEKLY	MONTHLY	YEARLY
1. LUBRICATION	ACCORDING TO TABLE 3	1	1-2		
2. ACCURACY	ACCORDING TO ACCUR A-INSPECTION CHART				1
3. CLEANING AND CORROSION PROTECTION	ALL SLIDGING SURFACES, TABLE SURFACE, T-SLOTS, SPINDLE NOSE, SPINDLE HOLE, ALL EXPOSED FINISHING SURFACES	1			
4. ADJUSTING OF GIBS	TABLE, SADDLE, SPINDLE, HEAD			2	
5. ADJUSTMENT OF FEEDING SCREWS	TABLE, SADDLE, SPINDLE, HEAD			1	
6. ADJUSTING OF FIXED MECHANISM	TABLE, SADDLE, SPINDLE HEAD			2	
7. LEVELLING AND TIGHTEN	FOUNDATION BOLT & SETTING SCREWS				2
8. TEMPERATURE OF BEARINGS CHECK UP	SPINDLE, GEAR BOX, BEARINGS MOTORS AND HYDRAULIC SYSTEM			1	
9. VIBRATION AND SOME ABNORMAL MOVEMENT CHECK UP	MOTORS, HYDRAULIC SYSTEM, GEARS AND OTHER TRANSMISSION		1		
10. ELECTRIC CIRCUIT CHECK UP	MOTORS, SWITCHES, CONNECTING POINTS OF WIRE, PUSH BUTTONS			1	



Table 7-1

Milling cutter	Work		Feed amount per tooth mm						
	Quality of materials	Brinell hardness HB	Face milling cutter	Plane milling cutter with helical teeth	Slotting saw and side milling cutter	End mill	Formed cutter	Saw blade milling cutter	
High-speed steel milling cutters	Special steel	Hard	0.1	0.075	0.075	0.05	0.05	0.05	0.025
		Tough	0.13	0.125	0.1	0.075	0.05	0.05	0.05
		Annealed	0.2	0.175	0.125	0.1	0.025	0.05	0.05
	Low carbon steel	Malleable	152 197	0.25	0.2	0.13	0.125	0.075	0.075
		Cuts well	150 180	0.3	0.25	0.175	0.13	0.1	0.035
	Cast iron	Hard	220 300	0.27	0.2	0.13	0.13	0.1	0.075
		Medium hard	150 250	0.325	0.25	0.175	0.175	0.1	0.0075
		Soft	150 180	0.4	0.325	0.225	0.2	0.125	0.1
	Brass and bronze	Hard	150 250	0.225	0.225	0.13	0.125	0.075	0.05
		Medium hard	100 150	0.35	0.35	0.2	0.175	0.1	0.075
		Cuts well	80 100	0.55	0.55	0.325	0.27	0.175	0.125
Magnesium and its alloys			0.55	0.45	0.325	0.27	0.175	0.125	
Aluminum and its alloys			0.55	0.45	0.325	0.27	0.175	0.125	
Plastic			0.375	0.3	0.225	0.175	0.125	0.1	

Table 7-2 (Continue)

Milling cutter	Work		Feed amount per tooth mm						
	Quality of materials	Brinell hardness (HB)	Face milling cutter	Plane milling cutter with helical teeth	Slotting saw and side milling cutter	End mill	Formed cutter	Saw blade milling cutter	
Sper-hard alloy milling cutter	Special steel	Hard	0.25	0.2	0.13	0.125	0.075	0.075	
		Tough	0.3	0.25	0.175	0.13	0.1	0.075	
		Annealed	0.35	0.27	0.2	0.175	0.1	0.1	
	Low - carbon steel	Malleable	152 197	0.35	0.27	0.2	0.175	0.1	0.1
		Cuts well	150 180	0.4	0.325	0.225	0.2	0.125	0.1
	Cast iron	Hard	220 300	0.3	0.25	0.175	0.13	0.1	0.075
		Medium hard	180 220	0.4	0.325	0.25	0.2	0.125	0.1
		Soft	150 180	0.5	0.4	0.3	0.25	0.13	0.125
	Brass and bronze	Hard	140 250	0.25	0.2	0.13	0.125	0.075	0.075
		Medium hard	100 150	0.3	0.25	0.175	0.13	0.1	0.075
		Cuts well	80 100	0.5	0.4	0.3	0.25	0.13	0.125
Magnesium and its alloys			0.4	0.45	0.3	0.25	0.13	0.125	
Aluminum and its alloys			0.4	0.45	0.3	0.25	0.13	0.125	
Plastic			0.3	0.3	0.225	0.175	0.125	0.1	