

The SHARP logo consists of the word "SHARP" in a bold, white, sans-serif font, centered within a solid blue rectangular background.

OPERATIONS MANUAL / PARTS LIST

Vertical-Horizontal Milling Machine  
(VH-25-DVS)

## Contents

|                                                     |    |
|-----------------------------------------------------|----|
| 1. Preface .....                                    | 1  |
| 2. Safety Rules.....                                | 2  |
| 2.1 Work Safety Codes .....                         | 2  |
| 2.2 Dangerous Zone for the Machine .....            | 2  |
| 3. Mechanical Specifications.....                   | 3  |
| 3.1 Mechanical Specification Sheet.....             | 3  |
| 3.2 Mechanical Noise .....                          | 4  |
| 3.3 Machine Dimensions .....                        | 4  |
| 4. Machine Installation Moving .....                | 5  |
| 4.1 Installation Environment Requirements .....     | 5  |
| 4.2 Power Requirement .....                         | 5  |
| 4.3 Moving.....                                     | 5  |
| 4.3.1 Equipment Moving Requirement .....            | 5  |
| 4.3.2 Lifting Method.....                           | 5  |
| 4.3.3 Precautions for Moving Machine .....          | 6  |
| 4.4 Machine Installation .....                      | 6  |
| 4.4.1 Machine Positioning .....                     | 6  |
| 4.4.2 Level Adjustment.....                         | 6  |
| 4.4.3 Precision Adjustment.....                     | 6  |
| 4.4.4 Check Prior to Start-up .....                 | 6  |
| 5. Machine Operation .....                          | 7  |
| 5.1 Machine Part Description .....                  | 7  |
| 5.2 Machine Head Description .....                  | 7  |
| 5.2.1 Head( Inverter) Description.....              | 7  |
| 5.2.2 Spindle gear shifting.....                    | 8  |
| 5.2.3 Manual Feed .....                             | 8  |
| 5.2.4 Manual Micro Feed.....                        | 8  |
| 5.2.5 Auto Feed.....                                | 8  |
| 5.3 Horizontal Milling Operation Instructions ..... | 9  |
| 5.4 Tri-axis Operating Instructions.....            | 10 |
| 5.4.1 Tri-axis Manual/Auto Feed Instructions.....   | 10 |
| 5.4.2 Fixing operation Instructions.....            | 10 |
| 5.5 Operating Panel Function .....                  | 11 |
| 6. Maintenance and Inspection.....                  | 12 |
| 6.1 Machine Lubrication Schedule .....              | 12 |
| 6.2 Cooling Fluid for Cutting .....                 | 13 |
| 6.3 Daily Maintenance.....                          | 13 |
| 6.4 Monthly Maintenance .....                       | 13 |
| 6.5 Seasonal Maintenance .....                      | 13 |
| 6.6 Semi-annual Maintenance .....                   | 13 |
| 6.7 Annual Maintenance .....                        | 13 |

|     |                                                                |    |
|-----|----------------------------------------------------------------|----|
| 7.  | Electrical Circuiting Diagram .....                            | 14 |
| 7.1 | Electrical Diagram .....                                       | 14 |
| 8.  | Assembly Drawing .....                                         | 16 |
| 8.1 | Head Upper (Inverter) Assembly Drawing / Parts List .....      | 16 |
| 8.2 | Head Lower Assembly Drawing / Parts List .....                 | 17 |
| 8.3 | Horizontal Milling Gearbox Assembly Drawing / Parts List ..... | 18 |
| 8.4 | X axis Assembly Drawing / Parts List.....                      | 19 |
| 8.5 | Y Axis Assembly Drawing.....                                   | 20 |
| 8.6 | Z Axis Assembly Drawing / Parts List.....                      | 21 |
| 8.7 | Telescopic Arm Assembly Drawing / Parts List .....             | 22 |

## 1. Preface

This equipment is a Vertical - Horizontal milling machine, which can be used in metal surface processing, such as drilling, milling, groove and boring etc., for reaching a predetermined surface shape. The materials and parts used to make the equipment have been subject to strict quality testing to ensure that the long-term use of the equipment can maintain the optimal mechanical characteristics and therefore maximize the processing efficiency.

This manual will provide users with instructions regarding equipment operation, maintenance, troubleshooting and precautions, as well as detailed assembly diagram as reference for parts replacement.

To ensure that the user can operate the equipment safely, please read this manual thoroughly before use, and **follow the maintenance and operation precautions** to prevent serious harm to the users and equipment.


## 2. Safety Rules

### 2.1 Work Safety Codes

- (1) The operator must receive the basic operation course and cannot operate the equipment before demonstrating the ability to safely operate it.
- (2) Operators are required to observe the warning signs affixed to the machine. For the warning signs on the machine, please do not arbitrarily damage them.
- (3) Before operating the machine, make sure that all switches and safety devices are in position and function properly.
- (4) To operate the machine, for safety reason, the operator should wear safety glasses and safety shoes, and remove all jewelry and excessively loose clothes.
- (5) Within the operator's activity range, no obstructing object is allowed.
- (6) Before operation, make sure that the workpiece and the tool are firmly locked to prevent accidents.
- (7) Do not place any tools or gauges on the machine's moving parts or on the control panel.
- (8) Do not bring any part of the body close to the machine's movement range while the machine is running.
- (9) Do not touch any switches or buttons when hands are wet.
- (10) When the machine is turned on for a long time, the lighting will become hot and may cause burns.
- (11) When adjusting or changing the belt, you must turn off the power first.
- (12) If the machine parts and components are loose, adjust immediately; otherwise, it may cause the disintegration of components and lead to accidents.
- (13) In the event of a power failure, the power supply should be switched off immediately.
- (14) The repair and installation of the machine should be carried out by a qualified or experienced technician.

### 2.2 Dangerous Zone for the Machine

In the operation of the machine, the range of machining is a very dangerous area, the parts with the following symbol "↔" are all within rotating or moving range, so be sure to alert operators and maintenance personnel to prevent serious harm.



### 3. Mechanical Specifications


#### 3.1 Mechanical Specification Sheet

| Model                            | Unit   | VH-25-DVS                                  |
|----------------------------------|--------|--------------------------------------------|
| <b>Travel</b>                    |        |                                            |
| Longitudinal travel (M./A.)      | mm     | 1000 (39.37 in)                            |
| Cross travel (M./A.)             | mm     | 400 (15.74 in)                             |
| Vertical travel (M./A.)          | mm     | 470 (18.5 in)                              |
| Slideway X/Y/Z                   | type   | △ / □ / □                                  |
| Quill travel                     | mm     | 140 (5.51 in)                              |
| Overarm travel                   | mm     | 700 (27.55 in)                             |
| Overarm swivel                   | degree | 360                                        |
| Quill swivel (R&L)/(F&B)         | degree | ±45 / Fixed                                |
| Dist. from spindle nose to table | mm     | 100-570 (3.93"-22.44")                     |
| Spindle centerline to column     | mm     | 180-880 (7.08"-34.64")                     |
| <b>Table</b>                     |        |                                            |
| Dimension                        | mm     | 1370x300 (53.93x11.81 in)                  |
| T-slots (Width x No. x Pitch)    | mm     | 16x3x70 (0.62x3x2.7 in)                    |
| Max. table load                  | kg     |                                            |
| <b>Spindle</b>                   |        |                                            |
| Vertical spindle speed           | rpm    | 60-4500 (Inverter)                         |
| Vertical feeds                   | mm/rev | 0.04/0.08/0.15 (0.0015, 0.0031, 0.0059 in) |
| Taper                            | type   | NT 40                                      |
| Quill diameter                   | mm     | 105                                        |
| Horizontal spindle speed         | rpm    | 60-1400 (Inverter)                         |
| Horizontal taper                 | type   | NT 40                                      |
| <b>Motor</b>                     |        |                                            |
| Vertical / Horizontal spindle    | HP     | 5                                          |
| X/Y/Z axis motor                 | HP     | 0.5 (gear ratio1:10)                       |
| <b>Feedrate</b>                  |        |                                            |
| X/Y axis speed                   | mm/min | 30-1000 (1.18-39.37 in)                    |
| Z axis speed                     | mm/min | 50-510 (1.96 – 20.07 in)                   |
| <b>Machine</b>                   |        |                                            |
| Space(L x W x H)                 | mm     | 2270x3100x2620 (89.37x122x103.1 in)        |
| Packing dimension(L x W x H)     | mm     | 1800x2280x2200 (70.86x89.76x86.6 in)       |
| Net Weight                       | kg     | 2200                                       |
| Gross Weight                     | kg     | 2400                                       |

### 3.2 Mechanical Noise

Before shipping out of the factory, this machine is manufactured at a noise level of less than 80 dB according to ISO 4871.

### 3.3 Machine Dimensions



## 4. Machine Installation Moving

### 4.1 Installation Environment Requirements

In general, the machine needs to have the following installation conditions:

- (1) There must be sufficient space for repair work, and the electrical box door can be opened without interference.
- (2) Make sure the ground strength is enough to support the machine load.
- (3) External temperature: 0~40°C
- (4) Relative humidity: 30%~95% (no condensation)
- (5) To facilitate future repair and maintenance, please keep appropriate space around the machine.

### 4.2 Power Requirement

- (1) Voltage supply: 200/220V ( $\pm 10\%$ )
- (2) Power frequency: 50/60Hz ( $\pm 1\text{Hz}$ )

### 4.3 Moving

#### 4.3.1 Equipment Moving Requirement


- (1) Refer to the table below for the weight of the machine. To lift the machine, it is necessary to have a strong hoist, a crane or a forklift and a qualified operator.

| Model         | Wight   |
|---------------|---------|
| YSM-26 series | 2200kgs |

- (2) If possible, please prepare some rags and wood blocks to protect the body to prevent injury.

#### 4.3.2 Lifting Method

The following figure shows the machine lifting method that the cross-arm bar can be adjusted to move the telescopic arm, during lifting, for the machine to be located in the center of gravity, to level and prevent risks.





### 4.3.3 Precautions for Moving Machine

- (1) Hoist operators are required to have license.
- (2) Lifting equipment (cranes, slings, rings, lifting clamps, etc.) should have sufficient strength to withstand the weight of the machine.
- (3) After the machine is lifted, the operator should not be exposed within the range of possible machine fall.
- (4) Check the machine again. If there are any loose parts, tighten it.
- (5) Lifting capacity of hoists and cranes should be sufficient. Before moving, achieve firm and stable state.


## 4.4 Machine Installation

### 4.4.1 Machine Positioning

- (1) Before the machine is put down, place the corner pads first at the machine supporting positions.
- (2) Please remove the rust-proof oil with clean cotton, and then apply lubricant.
- (3) Check if the oil feeder has enough oil.



### 4.4.2 Level Adjustment

- (1) Place two levels at the center of the table and place them at right angles.
- (2) Move table to the center of the stroke, check the bubble position in the level, use wrench to adjust bolts on the bottom base, until the bubble is centered in the level, as shown in the following figure.
- (3) Check if the oil feeder has enough oil.



### 4.4.3 Precision Adjustment

- (1) The table will move to the center of the moving path in X and Y axes. Move the head to the center of the table. The scale will be fixed to the end of the main spindle, so the needle will contact the table. Rotate the spindle and measure the right angle (cross), as shown in the figure below.
- (2) With the above-mentioned measurement values, use wrench to fine-tune the leveling for machine head to correct precision within machine specifications.




### 4.4.4 Check Prior to Start-up

To ensure the safety of users and machine, please do the following checks before starting up the machine to ensure machine precision and prolong its life.

- (1) Check if the lines, piping and all connectors are damaged.
- (2) Check that if the voltage, frequency and phase of the input power supply are correct.
- (3) Make sure that all switches can be properly operated without any obstacles.
- (4) Watch if any personnel is exposed in the danger zone.


## 5. Machine Operation

### 5.1 Machine Part Description



### 5.2 Machine Head Description


#### 5.2.1 Head( Inverter) Description



### 5.2.2 Spindle gear shifting

Operate handle (G), Turn the shift handle left to go high gear and right to go low gear.

The speed range varies from 55 to 570 RPM, and from 435 to 4500 RPM in high gear.




### 5.2.3 Manual Feed

Use the main spindle feed handle (I) to rotate the spindle up and down. Refer to Section 5.2.1 for stroke setting.

### 5.2.4 Manual Micro Feed

When using manual micro feed, turn the automatic feed knob (H) to neutral position, place the return lever (D) at (K) position, turn the manual feed hand wheel (C), forward for main spindle up, reverse for main spindle down. When the function is not used, set the return lever to (L).




### 5.2.5 Auto Feed

Auto feed procedures as follows:

- (1) Loosen main spindle handle (J).
- (2) Turn auto feed knob to in position.
- (3) Auto speed includes (0.04) / M (0.08) / H (0.15), which can be selected by speed knob (B) for desired feed speed.
- (4) Move the return lever (D) to (M) position.

- (5) When the main spindle motor runs forward (reverse), the manual feed hand wheel (C) will automatically rotate forward (reverse) to load the tool, and the screw on return lever is back to (O) position; if the screw is in (N) position, the hand wheel will rotate reverse (forward) to release the tool.

Caution: When auto feed is not activated, move the return lever (D) to (L) position. When the main spindle is running, do not change automatic feed knob (H) to in position, to prevent mechanism damage.




Other Cautions:

- (1) When replacing milling cutter, users are advised to shift the gear (G) to low gear.
- (2) Gear shift or change must be done when the motor is stopped to prevent users from danger.
- (3) For the main spindle feed action, loosen the main spindle fastening handle to prevent mechanism damage.
- (4) When the main spindle speed exceeds 3,000rpm, do not use automatic feed.

### 5.3 Horizontal Milling Operation Instructions

Manual gear shifting is available, providing a low-speed range of 215-1400 RPM and a high-speed range of 40-215 RPM.

A manual gear shift option is available via this button.




## 5.4 Tri-axis Operating Instructions

### 5.4.1 Tri-axis Manual/Auto Feed Instructions


Tri-axis manual handwheel operation, allowing movement in all axes.

(Warning: To enter manual(OUT) or automatic mode(IN), you must switch the handle.)




### 5.4.2 Fixing operation Instructions

When performing heavy-duty re-cutting, the relative axial direction may experience slippage. Therefore, it is recommended to fix the fixture to improve machine stability.




## 5.5 Operating Panel Function



## 6. Maintenance and Inspection

### 6.1 Machine Lubrication Schedule



| Lubrication position  | 1    | 2    | 3    | 4    | 5    |
|-----------------------|------|------|------|------|------|
| Check (hours)         | 8    | 8    | -    | -    | 8    |
| Add oil (days)        | -    | -    | 3    | -    | -    |
| Oil re-new (month)    | -    | -    | -    | 6    | -    |
| Specification for oil | VG32 | VG68 | VG68 | VG32 | VG32 |

Cautions: (1) Prior to lubricating, clean the oil feeder first.

(2) Please follow the above instructions on a regular basis for oil change, to keep the machine in a good state of lubrication, and prolong the machine life.


(3) No.3 Add 3-5cc of lubricant and shift between high and low gears to ensure proper lubrication.





## 6.2 Cooling Fluid for Cutting

- (1) Selecting cutting fluid depends on cutting conditions. Select the appropriate cutting fluid.
- (2) Inappropriate cutting fluid or improper use of the cutting fluid may result in serious damage to machine and personnel.
- (3) Clean water tank and filter periodically.



## 6.3 Daily Maintenance

- (1) Check if the liquid level in oil feeder is on the line.
- (2) Run the machine for 5 minutes before daily work.
- (3) At the end of every work day, clean the table and remove workpiece, and add a little lubricant in the table.
- (4) After work, loosen all fastening handles, move tri-axis sliding body to appropriate position; if the head deviates, move it to the position at zero degree.

## 6.4 Monthly Maintenance

- (1) Check if the wedge of each axle are normal.
- (2) Check if the feed screw and nut gap is normal.
- (3) Check if the fastening handles for the main spindles and all other axles are normal.

## 6.5 Seasonal Maintenance

- (1) Check if head brake, belt and gearshift mechanism are normal.
- (2) Clean or replace lubricant, strainer.

## 6.6 Semi-annual Maintenance

- (1) Check if motor runs normally or there is noise.
- (2) Immediately replace worn and unworkable parts found during maintenance.
- (3) Need to adjust mechanical leveling.

## 6.7 Annual Maintenance

- (1) Check mechanical precision, and determine if adjustment is needed.
- (2) Check if the oil line and the connector are good, if there is oil leak or damage.




## 8. Assembly Drawing

### 8.1 Head Upper (Inverter) Assembly Drawing / Parts List

| No. | Parts No. | Description         | Qty |
|-----|-----------|---------------------|-----|
| 1   |           | Inverter Motor      | 1   |
| 2   | 18J024C   | Spacer              | 1   |
| 3   | 18J024F   | Motor Pulley        | 1   |
| 4   | 18J023A   | Tooth Belt 8YU-880  | 1   |
| 5   | 18J026S   | Pulley Box          | 1   |
| 6   | 18G101B   | Side cover          | 1   |
| 7   | 18J001    | Drawbars            | 1   |
| 8   | 18J002    | Washer              | 1   |
| 9   | 18J003    | Upper Bearing Cover | 1   |
| 10  | BR008     | Ball Bearing (6209) | 1   |
| 11  | 18G101    | Side cover          | 1   |
| 12  | 18J009    | Locknuts (M50xP2.0) | 1   |
| 13  | 18J010A   | Spindle Pulley      | 1   |
| 14  | 18J011    | Pulley Seat         | 1   |
| 15  | 18J013    | Bearing Cover       | 1   |
| 16  | 16J051    | Brake Ring Screws   | 1   |
| 17  | 18J050    | Brake Ring          | 1   |
| 18  | BR009     | Ball Bearing (6210) | 2   |
| 19  | 18J053    | Brake Seat          | 1   |
| 20  | 16J068    | Brake block         | 2   |
| 21  | 16J037    | Locate Pins         | 1   |
| 22  | 16J047    | Locate Block lever  | 2   |
| 23  | 16J069    | Black Ball (5/16")  | 2   |
| 24  | 18J065    | Brake Lever         | 1   |
| 25  | 16J061    | Brake Stopper       | 1   |
| 26  | 16J038    | Fixed Ring          | 1   |
| 27  | 18J004    | Pulley shaft        | 1   |
| 28  | 16J016    | Spacer              | 1   |
| 29  | 18J040    | Spindle Gear        | 1   |
| 30  | 18J076    | Spring Slice        | 1   |
| 31  | 18J039    | Spindle Sleeve      | 1   |
| 32  | BR012     | Ball Bearing (6910) | 2   |
| 33  | 18J078    | Inner Spacer        | 1   |
| 34  | 18J079    | Outer Spacer        | 1   |
| 35  | 18J075    | Casing              | 1   |


| No. | Parts No. | Description         | Qty |
|-----|-----------|---------------------|-----|
| 36  | 18J058    | Spacer              | 1   |
| 37  | 18J056    | Locknuts (M50x2.0)  | 1   |
| 38  | 16J045    | Spring Fixed Pin    | 3   |
| 39  | 16J046    | Spring              | 3   |
| 40  | 16J035    | Platen              | 1   |
| 41  | 16J030    | Pulley              | 1   |
| 42  | 16J015    | Tooth Belt (560H8M) | 1   |
| 43  | 16J031    | Bearing Base        | 1   |
| 44  | BR002     | Ball Bearing (6203) | 2   |
| 45  | 16J083    | Gear (26T)          | 1   |
| 46  | 16J080    | Gear Shaft          | 1   |
| 47  | 18J028    | Gear Box            | 1   |
| 48  | 18J059    | Shift Shank         | 1   |
| 49  | 16J041    | Block               | 1   |
| 50  | 16J049    | Shift Lever         | 1   |
| 51  | 18J073    | Bolt                | 2   |
| 52  | 18J073A   | Bolt                | 1   |



## 8.2 Head Lower Assembly Drawing / Parts List


| No. | Parts No. | Description            | Qty |
|-----|-----------|------------------------|-----|
| 1   | 18B003    | Bevel Gear Shaft (12T) | 1   |
| 2   | 18B004    | Bushing                | 1   |
| 3   | 18B005    | Gear                   | 1   |
| 4   | 18B007    | Gaskets                | 1   |
| 5   | 18B008    | Gear (20T)             | 1   |
| 6   | 18B009    | Bevel Gear Shaft       | 1   |
| 7   | 18B015    | Bevel Gear (24T)       | 1   |
| 8   | 18B017    | Shake Seat             | 1   |
| 9   | 15B016    | Locate Pins            | 1   |
| 10  | 18B019    | Bushings               | 1   |
| 11  | 18B018    | Shaft                  | 1   |
| 12  | 18B023    | Knob                   | 2   |
| 13  | 18B036    | Gear (18T/12T)         | 1   |
| 14  | 18B040    | Gear (23T)             | 1   |
| 15  | BR031     | Needle roller bearings | 1   |
| 16  | 18B192A   | Head                   | 1   |
| 17  | 18B027    | Bushing                | 1   |
| 18  | 18B028    | Gear (17T/28T/22T)     | 1   |
| 19  | 18B033    | Bushing                | 1   |
| 20  | 18B034    | Spacer                 | 1   |
| 21  | 18B035    | Bevel Gear Shaft (12T) | 1   |
| 22  | 18B051    | Bevel Gear (24T)       | 1   |
| 23  | 18B050    | Clutch                 | 1   |
| 24  | 18B048    | Copper Bushings        | 1   |
| 25  | 18B049    | Bevel Gear (24T)       | 1   |
| 26  | 18B055    | Return lever           | 1   |
| 27  | 18B057    | Feed screw             | 1   |
| 28  | 18B042    | Bushing                | 1   |
| 29  | 18B063    | Shift fork             | 1   |
| 30  | 18B064    | Crank rod              | 1   |
| 31  | 15B060    | Locate Shaft           | 1   |
| 32  | 18B066    | Cover                  | 1   |
| 33  | 18B092    | Worm gear (30T)        | 1   |
| 34  | 18B080    | Clutch                 | 1   |
| 35  | 18B079    | Spring                 | 1   |
| 36  | 18B081    | Clutch Sleeve          | 1   |
| 37  | 18B078    | Spring Nuts            | 1   |
| 38  | 18B075    | Clutch Ring            | 1   |
| 39  | 15B074    | Screw Rod              | 1   |
| 40  | 18B096    | Bracket bar            | 1   |
| 41  | 18B099    | Clutch Ring            | 1   |
| 42  | 15B088A   | Spring                 | 1   |
| 43  | 15B088    | Spring                 | 1   |
| 44  | 15B089    | Locate Pins            | 1   |
| 45  | 18B118    | Jumper Sets            | 1   |
| 46  | 18B103    | Convex Rod             | 1   |

| No. | Parts No. | Description                 | Qty |
|-----|-----------|-----------------------------|-----|
| 47  | 18B104    | Handle                      | 1   |
| 48  | 15B024    | Black Ball (1/4")           | 1   |
| 49  | 15B120    | Spring                      | 1   |
| 50  | 15B121    | jumping bar                 | 1   |
| 51  | 18B106    | bracket                     | 1   |
| 52  | 18B113    | Handwheel Clutch            | 1   |
| 53  | 18B125    | Handle                      | 1   |
| 54  | 18B110    | Screw Rod                   | 1   |
| 55  | 15B146    | Springboard Pin             | 1   |
| 56  | 18B123    | Jumper Sets                 | 1   |
| 57  | 18B124    | jumping Bar                 | 1   |
| 58  | 15B145    | springboard                 | 1   |
| 59  | 18B090    | Gear Shaft Sleeve           | 1   |
| 60  | 18B166    | Toothed Rod                 | 1   |
| 61  | 15B168    | Tooth Fixed Block           | 1   |
| 62  | 18B178    | Spring                      | 1   |
| 63  | 18B177    | Spring Cover                | 1   |
| 64  | 18B176    | Gear seat                   | 1   |
| 65  | 18B175    | Hand seat                   | 1   |
| 66  | 15B172    | Tooth set screw             | 1   |
| 67  | 18B190    | Handle                      | 1   |
| 68  | 15B191    | Black Ball (3/8")           | 1   |
| 69  | 15B184    | Return Lever                | 1   |
| 70  | 15B183    | Ball-type jumper            | 1   |
| 71  | 15B185    | Ball-type Jumper Plug       | 1   |
| 72  | 18B148    | Tooth Fixed Tube            | 1   |
| 73  | 18B152A   | Spring                      | 1   |
| 74  | 18B153    | Fixed Pin                   | 1   |
| 75  | 18B149    | Fixed Handle                | 1   |
| 76  | 15B161    | Stop Nut                    | 1   |
| 77  | 15B162    | Fine-tune the nut           | 1   |
| 78  | 18B164    | Fine-tuning screw           | 1   |
| 79  | 18B163    | Stop Block                  | 1   |
| 80  | 18B128    | Dust Sheet                  | 1   |
| 81  | 18B142    | Tooth Tube (NT40)           | 1   |
| 82  | BR023     | Ball Bearing (6008)         | 2   |
| 83  | 18B129    | Locknuts (R8)               | 1   |
| 84  | BR013     | Angular Ball Bearing (7010) | 2   |
| 85  | 18B136    | Outer Spacer                | 1   |
| 86  | 18B137    | Inner Spacer                | 1   |
| 87  | 18B134    | Bearing Cover               | 1   |
| 88  | 18B133    | Tooth Nuts (NT40)           | 1   |
| 89  | 18B127    | NT40 Spindle                | 1   |
| 90  | 15B139    | Stop Block                  | 2   |



## 8.3 Horizontal Milling Gearbox Assembly Drawing / Parts List


| No. | Parts No. | Description               | Qty. |
|-----|-----------|---------------------------|------|
| 1   | 26H010    | Horizontal Spindle        | 1    |
| 2   | 26H009    | Cover                     | 1    |
| 3   | BR024     | Roller Bearings(32213U)   | 1    |
| 4   | 26H011    | Gear-A                    | 1    |
| 5   | 26H012    | Gear-B                    | 1    |
| 6   | 26C313    | Spacer                    | 1    |
| 7   | 26H131    | Locknuts                  | 1    |
| 8   | BR025     | Roller Bearings(4T-32209) | 1    |
| 9   | 26H132    | Locknuts                  | 1    |
| 10  | BR007     | Ball Bearing(6208)        | 1    |
| 11  | TC001     | Oil Seal(TC-40-55-8)      | 1    |
| 12  | 26H042    | Cover                     | 1    |
| 13  | 26H008    | Cover                     | 1    |
| 14  | 26H015    | Countershaft              | 1    |
| 15  | BR005     | Ball Bearing(6206)        | 3    |
| 16  | 26H016    | Gear-D                    | 1    |
| 17  | 26H017    | Gear-E                    | 1    |
| 18  | 26C314    | Spacer                    | 1    |
| 19  | 26H019    | Gear-G                    | 1    |
| 20  | 26H041    | Cover                     | 1    |
| 21  | BR027     | Ball Bearing(5205S)       | 1    |
| 22  | 26C316    | Gear-G                    | 1    |
| 23  | 26C315    | Pulley shaft              | 1    |
| 24  | BR006     | Ball Bearing(6207)        | 1    |
| 25  | 26H028    | Bearing base              | 1    |
| 26  | 26H027    | Cover                     | 1    |
| 27  | TC002     | Oil Seal                  | 1    |
| 28  | 26H004    | Pulley                    | 1    |
| 29  | 26H129    | V-belts                   | 3    |
| 30  | 26H133    | Locknuts                  | 1    |
| 31  | 26H006    | Pulley shaft              | 1    |
| 32  |           | Motor                     | 1    |
| 33  | 26H007    | Motor base                | 1    |






## 8.4 X axis Assembly Drawing / Parts List

| No. | Parts No. | Description          | Qty. |
|-----|-----------|----------------------|------|
| 1   | F003      | Table Sheet Metal    | 2    |
| 2   | 86C023B   | Table(54"x12")       | 1    |
| 3   | F010      | Gear cover           | 1    |
| 4   | F007      | Bevel Gear           | 1    |
| 5   | BR014     | Ball Bearing(7205)   | 2    |
| 6   | F018      | Bearing Cover        | 1    |
| 7   | F019      | Bearing housing      | 1    |
| 8   | F007A     | ( Bevel Gear         | 1    |
| 9   | BR001     | Ball Bearing(6004)   | 1    |
| 10  | F009      | Handwheel Shaft      | 1    |
| 11  | F011      | Bearing Sleeve       | 1    |
| 12  | BR003     | Ball Bearing(6204)   | 1    |
| 13  | F012      | Graduated Ring       | 1    |
| 14  | 15C068    | Scale Ring           | 1    |
| 15  | F006      | Locknuts             | 1    |
| 16  | 15C085    | Clutch               | 1    |
| 17  | F039      | Spring               | 1    |
| 18  | F004      | Handwheel Shaft      | 1    |
| 19  | F037      | Curved Handle        | 1    |
| 20  | 26C377    | Lead screw(1345L)    | 1    |
| 21  | 15C024A   | Angle Tooth Nuts(X)  | 1    |
| No. | Parts No. | Description          | Qty. |
| 22  | F016      | X-axis Nut Seat      | 1    |
| 23  | 15C024    | Angle Tooth Nuts (X) | 1    |
| 24  | 26C376    | Bearing housing      | 1    |
| 25  | 26C370    | Pulley(44T)          | 1    |
| 26  | 26C371    | spacer ring          | 1    |
| 27  | 26C372    | Clutch               | 1    |
| 28  | H5M560    | Tooth Belt           | 1    |
| 29  | 26C370    | Pulley(22T)          | 1    |
| 30  | 26C380    | Motor                | 1    |
| 31  | 26C378    | Cover                | 1    |
| 32  | 15C066    | Bearing Housing      | 1    |
| 33  | 26C381    | Cover plate          | 1    |
| 34  | 26C379    | Shaft                | 1    |
| 35  | 26C374    | Cover                | 1    |
| 36  | 20B041    | Block                | 1    |
| 37  | 16J049    | Shift Lever          | 1    |
| 38  | 16J069    | Black Ball (5/16")   | 1    |



## 8.5 Y Axis Assembly Drawing


| No. | Parts No. | Description            | Qty. |
|-----|-----------|------------------------|------|
| 1   | 15C041    | Locking Screw          | 6    |
| 2   | F035      | Track Scraper (back)   | 1    |
| 3   | 86C052A   | Saddle                 | 1    |
| 4   | F013A     | X axis Wedge           | 2    |
| 5   | F032      | X axis Stop Block      | 2    |
| 6   | F030      | Y axis Left Side Rail  | 1    |
| 7   | F008      | Y axis Wedge           | 3    |
| 8   | 18C046    | Stop Pin               | 2    |
| 9   | F033      | Fixed Handle           | 2    |
| 10  | F034      | Track Scraper (front)  | 1    |
| 11  | F031      | Y axis Right Side Rail | 1    |
| 12  | 15C024B   | Angle Tooth Nuts (Y)   | 1    |
| 13  | F017      | Y-axis Nut Seat        | 1    |
| 14  | 15C024C   | Angle Tooth Nuts (Y)   | 1    |



## 8.6 Z Axis Assembly Drawing / Parts List


| No. | Parts No. | Description            | Qty. |
|-----|-----------|------------------------|------|
| 1   | 26H045D   | Rear Cover Plate       | 1    |
| 2   | 26C098    | Body                   | 1    |
| 3   | 26C099    | Base                   | 1    |
| 4   | 18C153    | Feet Round Seat        | 4    |
| 5   | 16C103    | Lift Bracket           | 1    |
| 6   | 15C104    | Tooth Nuts(down)       | 1    |
| 7   | 16C082    | Lead Screw             | 1    |
| 8   | BR017     | (Thrust Bearing(51305) | 2    |
| 9   | BR004     | Ball Bearing(6205)     | 1    |
| 10  | 15C077    | Bevel gear             | 1    |
| 11  | 18C141    | Z axis Left Side Rail  | 1    |
| 12  | 15C041    | Thrust Bearing(51305)  | 6    |
| 13  | 18C047    | Z-axis wedge           | 2    |
| 14  | 18C140    | Y axis Right Side Rail | 1    |
| 15  | 18C055    | Z axis Wedge           | 1    |
| 16  | 18C057    | Stop Pin               | 2    |
| 17  | 15C037    | Fixed Handle           | 2    |
| 18  | 15C096    | Bevel Gear             | 2    |
| 19  | BR003     | Ball Bearing(6204)     | 6    |
| 20  | 26C304A   | shaft                  | 1    |
| 21  | 26C302    | bearing block          | 1    |
| 22  | 15C066    | Bearing cover          | 1    |
| 23  | 26C382    | Pulley(44T)            | 1    |
| 24  | H5M405    | Tooth Belt             | 1    |
| 25  | 26C380    | Pulley(22T)            | 2    |
| 26  | 26C303F   | Bearing housing        | 1    |
| 27  |           | Motor                  | 2    |
| 28  | 26C319B   | Cover                  | 1    |
| 29  | 26C062    | Lifting Seat           | 1    |
| 30  | 18C094    | Gear Shaft             | 1    |
| 31  | 15C092    | Bearing Housing        | 1    |
| 32  | 15C090    | Bearing Cover          | 1    |
| 33  | 15C088    | Dial Cover             | 1    |
| 34  | 15C087    | Scale Ring             | 1    |
| 35  | 15C086    | Locknuts               | 1    |
| 36  | 15C085    | Clutch                 | 2    |
| 37  | 18C084A   | Handle Sleeve          | 1    |
| 38  | 20C086    | Handle                 | 1    |

| No. | Parts No. | Description        | Qty. |
|-----|-----------|--------------------|------|
| 39  | 15C025    | Curved Handle      | 2    |
| 40  | 26C369    | Lead Screw (885L)  | 1    |
| 41  | 26C368    | Bearing housing    | 1    |
| 42  | BR014     | Ball Bearing(7205) | 2    |
| 43  | F018      | Bearing Cover      | 1    |
| 44  | 26C370    | Pulley(44T)        | 1    |
| 45  | H5M845    | Tooth Belt         | 1    |
| 46  | 26C371    | spacer ring        | 1    |
| 47  | 26C372    | Clutch             | 1    |
| 48  | 26C373    | Cover              | 1    |
| 49  | 26C375    | Shaft              | 1    |
| 50  | 26C374    | Cover              | 1    |
| 51  | 20B041    | Block              | 1    |
| 52  | 16J049    | Shift Lever        | 1    |
| 53  | 16J069    | Black Ball (5/16") | 1    |
| 54  | F012      | Graduated Ring     | 1    |
| 55  | 15C068    | Scale Ring         | 1    |
| 56  | F006      | Locknuts           | 1    |
| 57  | F004      | Handwheel Shaft    | 1    |
| 58  | 15B191    | Black Ball(3/8")   | 1    |
| 59  | 26H026    | Shift Handle       | 1    |
| 60  | 26H039    | Shift Seat         | 1    |
| 61  | 26H044    | Shift Cover        | 1    |
| 62  | 26H029    | Speed Shaft        | 1    |
| 63  | 26H032    | Shift Fork         | 1    |
| 64  | 26H037    | Toggle Jaw Mandrel | 1    |
| 65  | 26H038    | Toggle Claw        | 1    |
| 66  | 26H030    | Right Cover        | 1    |
| 67  | 26H186    | Support Frame      | 1    |
| 67  | 26H110    | Boom               | 1    |
| 69  | 26H111    | Cover              | 2    |
| 70  | 26H142    | Operation Box      | 1    |
| 71  | 18C145    | Handle             | 2    |
| 72  | 15C059    | Chip Board (H)     | 1    |
| 73  | 15C060    | Chip Board (M)     | 1    |
| 74  | 16C061    | Chip Board(L)      | 1    |



## 8.7 Telescopic Arm Assembly Drawing / Parts List

| No. | Parts No. | Description            | Qty. |
|-----|-----------|------------------------|------|
| 1   | 26C124    | Disc Holder(26)        | 1    |
| 2   | 26H175    | Spacer Ring            | 1    |
| 3   | 26H174    | Locking Bolts          | 1    |
| 4   | 26H177    | Disk Adapter           | 1    |
| 5   | 26H176    | Wedge                  | 1    |
| 6   | 26H173    | Solid Lock Ring        | 1    |
| 7   | 15C128    | Spacer Ring            | 1    |
| 8   | 26H170    | Gear                   | 1    |
| 9   | 26H172    | Toothed Rod            | 1    |
| 10  | 26H185    | Locking Screw          | 2    |
| 11  | 26H180    | Horizontal Shaft Seat  | 2    |
| 12  | 26H182    | Spacer Ring            | 2    |
| 13  | 26H181    | Bushing                | 2    |
| 14  | 26H184    | Locking Nut            | 2    |
| 15  | 26H183    | Horizontal Spindle Rod | 1    |
| 16  | 26H179    | Cover Plate            | 2    |
| 17  | 26C010F   | Telescopic Arms (26)   | 1    |
| 18  | 18C005    | Worm Shaft             | 1    |
| 19  | 18C004    | Spacer                 | 1    |
| 20  | 26H171    | Tooth Row              | 1    |
| 21  | 18C001    | Tilt Worm Gear         | 1    |





# SHARP

## PRECISION MACHINE TOOLS

Sharp Industries, Inc.

3501 Challenger Street

Torrance, CA 90503

Tel: 310-370-5990

Fax: 310-542-6162

Email: [info@sharpcnc.com](mailto:info@sharpcnc.com)

Parts: [parts@sharpcnc.com](mailto:parts@sharpcnc.com)

Sales: [sales@sharpcnc.com](mailto:sales@sharpcnc.com)

Support: [support@sharpcnc.com](mailto:support@sharpcnc.com)

[www.sharpcnc.com](http://www.sharpcnc.com)

